

Removal of Floor Finish:

1. Remove and/or protect all items in the room.
2. Tape off doorway thresholds, trim, or any other finished area that removal is not desired.
3. Pour PreCept PNC "Prep-n-Clean" into a clean mop bucket and add water at the proper ratio.
 - **Super Strength: 1:1 - Hard to Remove Semi-Permanent Finishes**
 - **Average Strength: 1:4 - Most Semi-Permanent Finishes**

Note: test floor in inconspicuous area before use.
4. Pour or mop on an appropriate amount of the solution on the floor, spread evenly with flat mop.
5. Check every 15 minutes until the floor finish looks like its softening or wrinkling from the floor.
6. Use Maroon Surface Prep Pad or 120-150 grit screens on a low speed machine to remove lifting urethane from surface.
7. Extract the PNC solution and removed finish from the surface.

Note: Reapply if needed, and missed areas repeat step 4-6.
8. Mix neutral solution of CLN-100 Neutral Cleaner 1 to 4 with water.
9. With a clean flat mop, wipe and liberally apply the solution on the floor surface with the CLN-100 solution. It is important to neutralize and remove the remaining PNC on the surface.
10. Clean water mop, no solution, the entire floor one to two times.
11. Allow floor to completely dry before applying the new coat of Praetorian's sealer and urethane.

